

Kansas Department of Agriculture
Division of Food Safety and Lodging
 1320 Research Park Drive, Manhattan, KS 66502
 (office) 785-564-6767 (fax) 785-564-6779

KANSAS LODGING ESTABLISHMENT INSPECTION REPORT

COMPLIANCE KEY: Y=in compliance; N=not in compliance; O=not observed; A=not applicable; C=corrected on-site during inspection; R=repeat violation.

NOTE: Inspector will check items of non-compliance and indicate deficiency.

Insp Date: 5/28/2015 **Business ID:** 96802LD
Business: ATCHISON MOTOR INN

Inspection: 13003344
Store ID:
Phone: 9133677000
Inspector: KDA13
Reason: 02 Follow-up
Results: No Follow-up

401 S 10TH ST
 ATCHISON, KS 66002

Time In / Time Out

Date	In	Out	Insp	Travel	Total	Mileage	Notes;
05/28/15	08:25 AM	08:45 AM	0:20	0:45	1:05	0	
Total:			0:20	0:45	1:05	0	

LODGING ESTABLISHMENT PROFILE

Rooms Licensed 43 Rooms Confirmed p
 Food Service None Rooms Insp. 1 No. of Violations 0 Insp. Notification Email
 Lic. Insp. _____ Insp. Sent To sunnypatel59@gmail.com

Rooms inspected 112

Address Verified p

Licensure Y N O A C R

- 1. Application and fees submitted.
- This item has Notes. See Footnote 1 at end of questionnaire.***
- 2. Complete plans submitted.
- 3. Variance request requirements met.

Food Service & Food Safety Y N O A C R

- 4. Food service for the general public licensed.
- 5. Commercially prepared and prepackaged food meets requirements.
- 6. Food service for overnight guests in compliance.

Imminent Health Hazard Y N O A C R

- 7. Operations discontinued and regulatory authority notified. p

General Requirements Y N O A C R

- 8. License posted and regulations in compliance. p
- This item has Notes. See Footnote 2 at end of questionnaire.***

KANSAS LODGING ESTABLISHMENT INSPECTION REPORT

General Requirements	Y	N	O	A	C	R
9. Hot water capacity sufficient to meet demand.
10. Adequate hand washing facilities supplied and accessible.
11. Toilet facilities: properly constructed, supplied and clean.
Personnel	Y	N	O	A	C	R
12. Employees excluded for health problems.
13. Employee hands clean and properly washed.
14. Employee clothing clean and in good repair.
Guest & Public Safety	Y	N	O	A	C	R
15. Facility structurally sound with repairs and maintenance to ensure safety.
16. Evacuation, fire, and carbon monoxide safety measures maintained.	p
<i>This item has Notes. See Footnote 3 at end of questionnaire.</i>						
Guest Rooms	Y	N	O	A	C	R
17. Guest rooms maintained clean and in good repair; toilet room and hand sink requirements met.	p
18. Guest rooms properly serviced and cleaned, cribs clean.
19. Coffeemakers and appliances approved, located, maintained clean and in good repair.
20. Guestroom free of insects, rodents, and pests.	p
21. Pet requirements met.
22. Door lock requirements met.	p
<i>This item has Notes. See Footnote 4 at end of questionnaire.</i>						
Dishware & Utensils	Y	N	O	A	C	R
23. Dishware and utensils cleaned, sanitized, handled and stored.
24. Cleaning and sanitizing requirements met.
Housekeeping & Laundry Facilities	Y	N	O	A	C	R
25. Carts properly designed, maintained and operated to prevent contamination.
26. Laundry facilities provided, maintained clean and in good repair.
27. Single use gloves available; storage areas maintained.
Poisonous or Toxic Materials	Y	N	O	A	C	R
28. Toxic substances allowed, stored, located, labeled and used.
Public Indoor Areas	Y	N	O	A	C	R
29. Public indoor areas; equipment and furnishings maintained, clean and in good repair.
30. Fitness rooms bathhouse and spa maintained clean and in good repair.
Ice & Ice Dispensing	Y	N	O	A	C	R
31. Ice from approved source dispensed by sanitary methods.
32. Ice machines/buckets properly cleaned, sanitized, maintained and used.
Exterior Premises	Y	N	O	A	C	R
33. Exterior areas including playgrounds and storage areas clean and good repair.

KANSAS LODGING ESTABLISHMENT INSPECTION REPORT

Exterior Premises	Y	N	O	A	C	R
--------------------------	---	---	---	---	---	---

34. Refuse containers maintained; vector control measures implemented, pets.

Swimming Pools, RWF's & Hot Tubs	Y	N	O	A	C	R
---	---	---	---	---	---	---

35. Facility properly designed, maintained sanitary and safe.

36. Water quality, clarity requirements met.

37. Fecal, vomit, and body fluid response requirements met.

38. Operation & maintenance procedures met.

Water Supply System	Y	N	O	A	C	R
----------------------------	---	---	---	---	---	---

39. Potable water supply used.

40. Boil water advisories properly addressed.

Sewage Systems	Y	N	O	A	C	R
-----------------------	---	---	---	---	---	---

41. Sewage and waste water properly disposed.

Electrical Systems	Y	N	O	A	C	R
---------------------------	---	---	---	---	---	---

42. Electrical properly installed and maintained.

Plumbing Systems	Y	N	O	A	C	R
-------------------------	---	---	---	---	---	---

43. Plumbing properly installed, supplied and maintained. p

44. Proper use of backflow devices and testing requirements.

HVAC Systems	Y	N	O	A	C	R
---------------------	---	---	---	---	---	---

45. Approved equipment installed and maintained in good repair.

46. Safety issues for gas, electric and ventilation met.

Swimming Pool, Hot Tub, RWF Survey	In Operation	Not in Operation	None
---	--------------	------------------	------

Indoor Pool i i i

Outdoor Pool i i i

Indoor Hot Tub i i i

Outdoor Hot Tub i i i

Indoor RWF i i i

Outdoor RWF i i i

Swimming Pool, Hot Tub, RWF Details
--

EDUCATIONAL MATERIALS

The following educational materials were provided: ..

KANSAS LODGING ESTABLISHMENT INSPECTION REPORT

Footnote 1

Notes:

Critical (Critical); Non Critical Violation (NC); Corrected On Site (COS); Cold Hold (CH); Walk In Cooler (WIC); Person In Charge (PIC); Walk In Freezer (WIF); Steam Table (ST); Potentially Hazardous Food (PHF); Hot Hold (HH); Ready To Eat (RTE); Make Table (MT); Reach In Cooler (RIC); Voluntary Closure (VC); Bare Hand Contact (BHC); Chlorine (Cl); Parts Per Million (PPM); Voluntary Destruction (VD); Risk Control Plan (RCP); Reach In Freezer (RIF); Degrees Fahrenheit (F); Quaternary Compounds (QT); Notice of Non Compliance (NONC); Hot Box (HB)

The sheet rock on both sides of the walls were removed the leak was fixed. Room is still being worked on.

Footnote 2

Notes:

Licesne is posted.

Footnote 3

Notes:

Smoke detector is working

Footnote 4

Notes:

New door lock was placed on the door.