

**Kansas Department of Agriculture**  
**Division of Food Safety and Lodging**  
 1320 Research Park Drive, Manhattan, KS 66502  
 (office) 785-564-6767 (fax) 785-564-6779

**KANSAS LODGING ESTABLISHMENT INSPECTION REPORT**

COMPLIANCE KEY: Y=in compliance; N=not in compliance; O=not observed; A=not applicable; C=corrected on-site during inspection; R=repeat violation.

NOTE: Inspector will check items of non-compliance and indicate deficiency.

**Insp Date:** 5/25/2011      **Business ID:** 105042LD  
**Business:** SUPER 8 MOTEL  
 SUNNY PATEL  
 509 S 9TH ST  
 ATCHISON, KS 66002

**Inspection:** 75001231  
**Store ID:**  
**Phone:** 9133677666  
**Inspector:** KDA75  
**Reason:** 03 Complaint  
**Next Inspection on or near:** 5/24/2012

**Results:** No Follow-up

**Time In / Time Out**

Date	In	Out	Insp	Travel	Total	Mileage	Notes;
05/25/11	10:30 AM	01:00 PM	2:30	0:00	2:30	0	
<b>Total:</b>			2:30	0:00	2:30	0	

**LODGING ESTABLISHMENT PROFILE**

Rooms Licensed 45      Rooms Confirmed p  
 Food Service \_\_\_\_\_ Guest Rooms 45      No. of Violations 0      Insp. Notification Print  
    Insp.  
 Lic. Insp. No

Rooms inspected 110-204-206-306

Address Verified p

Licensure	Y	N	O	A	C	R
1. Application and fees submitted.	p	..	..	..	..	..
2. Complete plans submitted.	..	..	..	p	..	..
3. Variance request requirements met.	..	..	..	p	..	..
Food Service & Food Safety	Y	N	O	A	C	R
4. Food service for the general public licensed.	..	..	..	p	..	..
5. Commercially prepared and prepackaged food meets requirements.	..	..	..	p	..	..
6. Food service for overnight guests in compliance.	p	..	..	..	..	..
Imminent Health Hazard	Y	N	O	A	C	R
7. Operations discontinued and regulatory authority notified.	p	..	..	..	..	..
General Requirements	Y	N	O	A	C	R
8. License posted and regulations in compliance.	p	..	..	..	..	..
9. Hot water capacity sufficient to meet demand.	p	..	..	..	..	..

# KANSAS LODGING ESTABLISHMENT INSPECTION REPORT

General Requirements	Y	N	O	A	C	R
10. Adequate hand washing facilities supplied and accessible.	p	..	..	..	..	..
11. Toilet facilities: properly constructed, supplied and clean.	p	..	..	..	..	..
Personnel	Y	N	O	A	C	R
12. Employees excluded for health problems.	p	..	..	..	..	..
13. Employee hands clean and properly washed.	p	..	..	..	..	..
14. Employee clothing clean and in good repair.	p	..	..	..	..	..
Guest & Public Safety	Y	N	O	A	C	R
15. Facility structurally sound with repairs and maintenance to ensure safety.	p	..	..	..	..	..
16. Evacuation, fire, and carbon monoxide safety measures maintained.	p	..	..	..	..	..
Guest Rooms	Y	N	O	A	C	R
17. Guest rooms maintained clean and in good repair; toilet room and hand sink requirements met.	p	..	..	..	..	..
18. Guest rooms properly serviced and cleaned, cribs clean.	p	..	..	..	..	..
19. Coffeemakers and appliances approved, located, maintained clean and in good repair.	p	..	..	..	..	..
20. Guestroom free of insects, rodents, and pests.	p	..	..	..	..	..
<b><i>This item has Notes. See Footnote 1 at end of questionnaire.</i></b>						
21. Pet requirements met.	p	..	..	..	..	..
22. Door lock requirements met.	p	..	..	..	..	..
Dishware & Utensils	Y	N	O	A	C	R
23. Dishware and utensils cleaned, sanitized, handled and stored.	..	..	p	..	..	..
24. Cleaning and sanitizing requirements met.	..	..	p	..	..	..
Housekeeping & Laundry Facilities	Y	N	O	A	C	R
25. Carts properly designed, maintained and operated to prevent contamination.	p	..	..	..	..	..
26. Laundry facilities provided, maintained clean and in good repair.	..	..	p	..	..	..
27. Single use gloves available; storage areas maintained.	..	..	p	..	..	..
Poisonous or Toxic Materials	Y	N	O	A	C	R
28. Toxic substances allowed, stored, located, labeled and used.	..	..	p	..	..	..
Public Indoor Areas	Y	N	O	A	C	R
29. Public indoor areas; equipment and furnishings maintained, clean and in good repair.	p	..	..	..	..	..
30. Fitness rooms bathhouse and spa maintained clean and in good repair.	..	..	..	p	..	..
Ice & Ice Dispensing	Y	N	O	A	C	R
31. Ice from approved source dispensed by sanitary methods.	p	..	..	..	..	..
32. Ice machines/buckets properly cleaned, sanitized, maintained and used.	p	..	..	..	..	..
Exterior Premises	Y	N	O	A	C	R
33. Exterior areas including playgrounds and storage areas clean and good repair.	p	..	..	..	..	..
34. Refuse containers maintained; vector control measures implemented, pets.	p	..	..	..	..	..
Swimming Pools, RWF's & Hot Tubs	Y	N	O	A	C	R

# KANSAS LODGING ESTABLISHMENT INSPECTION REPORT

Swimming Pools, RWF's & Hot Tubs	Y	N	O	A	C	R
35. Facility properly designed, maintained sanitary and safe.	..	..	..	p	..	..
36. Water quality, clarity requirements met.	..	..	..	p	..	..
37. Fecal, vomit, and body fluid response requirements met.	..	..	..	p	..	..
38. Operation & maintenance procedures met.	..	..	..	p	..	..

Water Supply System	Y	N	O	A	C	R
39. Potable water supply used.	p	..	..	..	..	..
40. Boil water advisories properly addressed.	..	..	p	..	..	..

Sewage Systems	Y	N	O	A	C	R
41. Sewage and waste water properly disposed.	p	..	..	..	..	..

Electrical Systems	Y	N	O	A	C	R
42. Electrical properly installed and maintained.	p	..	..	..	..	..

Plumbing Systems	Y	N	O	A	C	R
43. Plumbing properly installed, supplied and maintained.	p	..	..	..	..	..
44. Proper use of backflow devices and testing requirements.	p	..	..	..	..	..

HVAC Systems	Y	N	O	A	C	R
45. Approved equipment installed and maintained in good repair.	p	..	..	..	..	..
46. Safety issues for gas, electric and ventilation met.	p	..	..	..	..	..

Swimming Pool, Hot Tub, RWF Survey	In Operation	Not in Operation	None
Indoor Pool	i	i	x
Outdoor Pool	i	i	x
Indoor Hot Tub	i	i	x
Outdoor Hot Tub	i	i	x
Indoor RWF	i	i	x
Outdoor RWF	i	i	x

Swimming Pool, Hot Tub, RWF Details
-------------------------------------

EDUCATIONAL MATERIALS
-----------------------

The following educational materials were provided: ..

# KANSAS LODGING ESTABLISHMENT INSPECTION REPORT

## **Footnote 1**

### **Notes:**

#### COMPLAINT HISTORY

Possible Bed Bug Bites-Room 206 Super 8 Motel Atchison Kansas

#### INSPECTION FINDINGS

The Atchison County Health Department received a complaint from a guest of possible bed bug bites secondary to a stay in Room 206 at the Super 8 Motel in Atchison Kansas. They transferred the complaint to the Kansas Department of Agriculture Division of Food Safety & Lodging.

An on-site inspection was completed of Room 206. The nightstand and chairs were inverted and examined; the headboard was removed and examined as were the seams of the mattress and box springs. The linen was examined along with the pillow cases and pillows. No evidence of a bed bug infestation was found. The PIC of the Super 8 advised prior to our arrival and based on a complaint by a guest they called an LPCO (ECO-LAB Pest Control) to complete an inspection of Room 206. They were not able to locate any bed bug activity. Additional Rooms 110-204-306 were also randomly inspected and no evidence any bed bug activity was found.

The PIC was advised to contact their LPCO and have them fax a copy of their bed bug inspection report for Room 206 to KDA Division of Food Safety & Lodging 1-785-296-6522 and the Atchison County Health Department.